

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Rio(YB)/--

VIN: KNADB512LK6324007

Odometer Reading: 152795km

License Plate: JC61SXGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V13.50

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned(10)

System	Status/DTC
ENG (Engine)	0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	0
AB (Airbag)	1
CLU (Cluster Module)	0
I-TPMS (I-Tire Pressure Monitoring System)	0
A/C (Air Conditioner)	0
BCM (Body Control)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B2500:00	Warning lamp failure	History

Technician Notes

2016265337

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.