

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Rio(YB)/--
VIN: KNADB512LL6390470

Odometer Reading: 199209KM
License Plate: BF62DDZN

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
ENG (Engine)	 0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
I-TPMS (I-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
BCM (Body Control)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1

DTC (2)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes

2017304207

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.