

# Kia VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Kia/Rio(UB)/--

VIN: KNADN511LG6758805

Odometer Reading: 134289

License Plate: FC47GZGP

## Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

## Device information








Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V13.50

Repair Order Number: --

## System Scanned ( 7 )

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
BCM (Body Control)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0

## DTC ( 1 )

### AB (Airbag) ( 1 DTC )

DTC	Description	Status
B1102:00	Battery voltage low	History

## Technician Notes

2016309246

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.