

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Rio(UB)/--

VIN: KNADN511LG6763118

Odometer Reading: 121880

License Plate: FJ16RFGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information



Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V13.50

Repair Order Number: --

System Scanned(7)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 2
AB (Airbag)	 2
BCM (Body Control)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0

DTC (4)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1102	Battery voltage low	History
C1604	ECU hardware Error	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1352:00	Passenger airbag (PAB) resistance too high (1st Stage)	Active

Technician Notes

2016256681

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.