



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250417110456
Test Time: 2025-04-17 11:04:56
Technician: Andrick

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Pride(UB)/--
VIN: KNADN512LD6815841

Odometer Reading: 168061
License Plate: CH08PVG

Customer Information

Name: Dekra MFC AUCTION HOUSE








Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.86

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(7)

System	Status/DTC
ENG (Engine)	 0
ABS/VDC (Anti Lock Brake system/Vehicle Dynamic Control)	 0
AB (Airbag)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0
CODE (Transmitter Code Saving)	 0
IMMO (Immobilizer)	 0

DTC (0)

Technician Notes

2016847401

Customer name: _____
Technician: _____
Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

