



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250730114815
Test Time: 2025-07-30 11:48:15
Technician: Clive

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Pride(UB)/--
VIN: KNADN512LG6767023

Odometer Reading: 59208
License Plate: JJX551MP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.90

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
ENG (Engine)	 1
ABS/VDC (Anti Lock Brake system/Vehicle Dynamic Control)	 2
AB (Airbag)	 2
A/C (Air Conditioner)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0
CODE (Transmitter Code Saving)	 0
IMMO (Immobilizer)	 0

DTC (5)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0562	System voltage low	History

ABS/VDC (Anti Lock Brake system/Vehicle Dynamic Control) (2 DTCs)

DTC	Description	Status
C1207	Left rear wheel speed sensor (WSS) range/performance/Intermittent	History
C1210	Right rear vehicle speed sensor (VSS) range/performance/Intermittent	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History



B2500:00

Warning lamp failure

History

Technician Notes

2016963143

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.