

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/K3(YD)/--

VIN: KNAFZ613ME5152615

Odometer Reading: 115725

License Plate: DM33MRGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V13.50

Repair Order Number: --



System Scanned(11)

System	Status/DTC
ENG (Engine)	✓ 0
A/T (Transaxle)	✓ 0
ABS/VDC (Anti Lock Brake system/Vehicle Dynamic Control)	✓ 0
AB (Airbag)	✗ 1
CLU (Cluster Module)	✓ 0
A/C (Air Conditioner)	✓ 0
EPS (Motor Driven Power Steering)	✗ 1
SMK (Smart Key Unit)	✓ 0
BCM (Body Control)	✓ 0
CODE (Transmitter Code Saving)	✓ 0
SJB (Smart Junction Block)	✓ 0



DTC (2)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History

Technician Notes

2016311715

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.