



Shop: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240926113832

Test Time: 2024-09-26 11:38:32

Technician: Werner

GreatWall VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/GreatWall/Haval H1/--

VIN: LGWED2A33LE621200

Odometer Reading: 68500

License Plate: KDY591MP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V10.80

Serial Number: VB8GJCC01514

Repair Order Number: --

System Scanned(2)

System	Status/DTC
SRS (Airbag System)	3
IMMO (Immobilizer)	0

DTC (3)

SRS (Airbag System) (3 DTCs)

DTC	Description	Status
B1091	Warning lamp short to ground	
B1024	Driver front airbag high resistance	
B1011	Battery voltage low	

Technician Notes

2016546840

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

