Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261022090241
Test Time: 2026-10-22 09:02:41
Technician: Werner

HAVAL VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/HAVAL/Haval H1/--
VIN: LGWED2A3XLE621257

Odometer Reading: 137078
License Plate: JM89TYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (2)

System	Status/DTC
SRS (Supplemental Restraint System)	4
IMMO (Immobilizer)	0

DTC (4)

SRS (Supplemental Restraint System) (4 DTCs)

DTC	Description	Status
B1091	Warning lamp short to ground	
B1024	Driver front airbag high resistance	
B1011	Battery voltage low	
B1029	Passengers front airbag high resistance	

Technician Notes

2017315657

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.