

JAC VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/JAC/JAC pick-up truck/T8/--
VIN: LJ11PABD6MC020193

Odometer Reading: 132219
License Plate: KF56LVGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V8.51

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (2)

System	Status/DTC
EMS (Engine System)-HFC4DB2-2E (2.0CTI) Diesel Engine	 0
ABS (Antilock Brake System)	 0

DTC (0)

Technician Notes

2017298716

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.