Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261026135135
Test Time: 2026-10-26 13:51:35
Technician: Andrick

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Pegas/Soluto (AB)/--
VIN: LJD0AA29LP0203372
Odometer Reading: 84663
License Plate: FYR158L

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
ENG (Engine)	0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	1
AB (Airbag)	2
CLU (Cluster Module)	0
TPMS (Tire Pressure Monitoring System)	1
BCM (Body Control)	0
IMMO (Immobilizer)	1
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	1

DTC (6)

ABS/ESC (Anti Lock Brake/Electronic Stability Control) (1 DTC)

DTC	Description	Status
C1102:01	Battery voltage low	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	History

TPMS (Tire Pressure Monitoring System) (1 DTC)

DTC	Description	Status
C1102:01	Battery voltage low	History

IMMO (Immobilizer) (1 DTC)

DTC	Description	Status

P1678	Engine management system (EMS) no request	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes

2017317439

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.