



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250423091606  
Test Time: 2025-04-23 09:16:06  
Technician: Werner

# Mahindra VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Mahindra/Xuv700/--  
VIN: MA1NF2ZFFP6078839

Odometer Reading: 29395  
License Plate: LF89VCGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE






Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V2.71

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 5 )

| System  | Status/DTC  |
|---|---|
| Engine management system                                |  7   |
| Transmission control unit                               |  2   |
| Anti-Lock braking system / Electronic stability program |  5  |
| Passive keyless entry                                   |  4 |
| Infotainment system                                     |  6 |

## DTC ( 24 )

### Engine management system ( 7 DTCs )

| DTC     | Description                             | Status |
|---------|---|--------|
| U113200 | Please refer to vehicle service manual. | Other  |
| U110500 | IC node absent                          | Other  |
| U110800 | Please refer to vehicle service manual. | Other  |
| U20AB00 | Please refer to vehicle service manual. | Healed |
| U20AC00 | Please refer to vehicle service manual. | Healed |
| U201600 | Please refer to vehicle service manual. | Healed |
| P056200 | Please refer to vehicle service manual. | Other  |

### Transmission control unit ( 2 DTCs )

| DTC     | Description                             | Status  |
|---------|---|---------|
| P333904 | Please refer to vehicle service manual. | Current |
| U20E400 | Please refer to vehicle service manual. | Healed  |

### Anti-Lock braking system / Electronic stability program ( 5 DTCs )

| DTC | Description | Status |
|-----|-------------|--------|
|-----|-------------|--------|



|         |   |        |
|---------|---|--------|
| C002016 | Return flow pump supply error           | Other  |
| C114446 | Please refer to vehicle service manual. | Healed |
| C117000 | Please refer to vehicle service manual. | Healed |
| U100400 | Please refer to vehicle service manual. | Other  |
| U300004 | ECU internal failure                    | Other  |

**Passive keyless entry ( 4 DTCs )**

| DTC     | Description                             | Status |
|---------|---|--------|
| B12F516 | Power supply is under voltage           | Healed |
| B132C12 | Please refer to vehicle service manual. | Healed |
| B133016 | Please refer to vehicle service manual. | Other  |
| U180100 | Bus integrity check                     | Healed |

**Infotainment system ( 6 DTCs )**

| DTC     | Description                             | Status  |
|---------|---|---------|
| B202416 | Please refer to vehicle service manual. | Healed  |
| B102100 | MIC communication error                 | Other   |
| B103200 | Please refer to vehicle service manual. | Other   |
| B147255 | Please refer to vehicle service manual. | Current |
| B148600 | Please refer to vehicle service manual. | Healed  |
| U111500 | Please refer to vehicle service manual. | Other   |

**Technician Notes**

2016851234

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.