Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261026145516
Test Time: 2026-10-26 14:55:16
Technician: Werner

Mahindra VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mahindra/Scorpio/--
VIN: MA1RA2CY2T2036361

Odometer Reading: 7050
License Plate: HPV011L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V3.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (4)

System	Status/DTC
Engine management system	0
Instrument cluster	0
Mahindra body function module	2
Immobiliser	0

DTC (2)

Mahindra body function module (2 DTCs)

DTC	Description	Status
B116715	Please refer to vehicle service manual.	Current
B116915	Please refer to vehicle service manual.	Current

Technician Notes

2017317486

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.