



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250522102241
Test Time: 2025-05-22 10:22:41
Technician: Travino

Mahindra VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mahindra/Scorpio/--
VIN: MA1RA2VK2R2A13418

Odometer Reading: 14137
License Plate: HGG437L

Customer Information

Name: Dekra MFC AUCTION HOUSE





Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V2.71

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(4)

System	Status/DTC
Engine management system	 2
Instrument cluster	 0
Mahindra body function module	 0
Immobiliser	 0

DTC (2)

Engine management system (2 DTCs)

DTC	Description	Status
P134000	Indicates if a twin mass fly wheel resonance shutoff condition is active	Healed
P164100	Software reset error 3	Healed

Technician Notes

2016886603

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

