

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Vitara Brezza/--
VIN: MA3NYFJ1S00837648

Odometer Reading: 115903
License Plate: KH11LHGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
ECM/PCM(Engine/powertrain)	 0
TCM(Transmission Control Module)	 0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	 0
SRS(Airbag)	 0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	 4
CGW(Central gateway control module)	 0
EPS(Power steering)	 0
A/C(Air-Conditioning)	 1
BCM(Body Control Module)	 0
IMMO(Immobilizer and/or keyless system)	 1

DTC (6)

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (4 DTCs)

DTC	Description	Status
B1864	Left rear parking sensor	History
B1865	Rear/center/left parking sensor	History
B1866	Rear/center/right parking sensor	History
B1867	Right rear parking sensor	History

A/C(Air-Conditioning) (1 DTC)

DTC	Description	Status
B1504	Solar sensor and/or its circuit fault	Current

IMMO(Immobilizer and/or keyless system) (1 DTC)

DTC	Description	Status
B1134	Remote controller battery low	History

Technician Notes
2017305114

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.