

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/S-presso/--

VIN: MA3RFL61S00426915

Odometer Reading: 100881

License Plate: LD48LKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V4.91

Serial Number: VB8GJCC01509

Repair Order Number: --



System Scanned (7)

System	Status/DTC
ECM/PCM(Engine/powertrain)	✓ 0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	✗ 3
SRS(Airbag)	✓ 0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	✓ 0
EPS(Power steering)	✓ 0
BCM(Body Control Module)	✓ 0
SMK(Immobilizer and/or keyless system)	✓ 0



DTC (3)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (3 DTCs)

DTC	Description	Status
C1157-1C	Power supply voltage abnormal	History
C1161-07	Pump motor circuit	History
U1082-87	Lost communication with ENG A-STOP control module	History

Technician Notes

2017298257

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.