

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Celerio/--

VIN: MA3TFC62S00148906

Odometer Reading: 45643

License Plate: JZN887EC

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V4.91

Serial Number: VB8GJCC01509

Repair Order Number: --



System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	✓ 0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	✗ 3
SRS(Airbag)	✓ 0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	✗ 3
CGW(Central gateway control module)	✓ 0
EPS(Power steering)	✓ 0
BCM(Body Control Module)	✓ 0
SMK(Immobilizer and/or keyless system)	✓ 0



DTC (6)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (3 DTCs)

DTC	Description	Status
C1157-1C	Power supply voltage abnormal	History
C1161-07	Pump motor circuit	History
U1082-87	Lost communication with ENG A-STOP control module	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (3 DTCs)

DTC	Description	Status
B1852	Rear parking sensor communication bus error	History
B1865	Rear/center/left parking sensor	History
B1866	Rear/center/right parking sensor	History

Technician Notes

2017278397

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.