Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/KA / Figo/--
VIN: MAJGXXMTKGKK75801

Odometer Reading: 119068
License Plate: KKC804NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
PCM(Powertrain control module)	1
ABS(Anti-lock brake system)	2
RCM(Restraint control module)	2
IPC(Instrument panel control module)	1
ACM(Audio control module)	1
BCMii(Body control module) ADAS	5
HVAC(Heating ventilation air conditioning)	1
PSCM(Power steering control module)	0

DTC (13)

PCM(Powertrain control module) (1 DTC)

DTC	Description	Status
P115E:00-28	Throttle Actuator Control Throttle Body Air Flow Trim at Max Limit	CMDTCs

ABS(Anti-lock brake system) (2 DTCs)

DTC	Description	Status
C0031:15-2B	Left Front Wheel Speed Sensor	CMDTCs
U3003:16-68	Battery voltage	CMDTCs

RCM(Restraint control module) (2 DTCs)

DTC	Description	Status
U0401:00-8B	Invalid Data Received from Electronic Control Module/Powertrain Control Module A	CMDTCs
U3003:16-08	Battery voltage	CMDTCs

IPC(Instrument panel control module) (1 DTC)

DTC	Description	Status
U0401:00-0A	Invalid Data Received from Electronic Control Module/Powertrain Control Module A	CMDTCs

ACM(Audio control module) (1 DTC)

DTC	Description	Status
U3003:16-08	Battery voltage	CMDTCs

BCMii(Body control module) (5 DTCs)

DTC	Description	Status
B10F4:15-0A	Right front position lamp	CMDTCs
B1131:08-08	Wiper motor module	CMDTCs
B121A:11-48	Keypad Illumination Output	CMDTCs
B1313:15-0A	Interior Lighting Output	CMDTCs
B1444:15-0A	Left rear stop/position lamp output	CMDTCs

HVAC(Heating ventilation air conditioning) (1 DTC)

DTC	Description	Status
U0401:00-0A	Invalid Data Received from Electronic Control Module/Powertrain Control Module A	CMDTCs

Technician Notes

2017314567

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.