



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231214130618
Test Time: 2023-12-14 13:06:18
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Atos/--

VIN: MALAF51CLLM092647

Odometer Reading: 56824km

License Plate: JH65SZGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V13.40

Repair Order Number: --

System Scanned(6)

System	Status/DTC
ENG (Engine)	 0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	 0
AB (Airbag)	 2
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (2)

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History

Technician Notes

2016203829

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.