

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Atos/--

VIN: MALAF51CLNM151166

Odometer Reading: 32959km

License Plate: KD13JNGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information







Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V13.40

Repair Order Number: --

System Scanned(6)

System	Status/DTC
ENG (Engine)	 1
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	 1
AB (Airbag)	 2
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (4)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0068:00	Manifold absolute pressure (MAP)/Mass air flow (MAF) - Throttle position sensor correlation	Pending

ABS/ESC (Anti Lock Brake/Electronic Stability Control) (1 DTC)

DTC	Description	Status
C1102:01	Battery voltage low	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History

Technician Notes

2016209356

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.