

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Atos/--
VIN: MALAF51CLNM181491

Odometer Reading: 58737KM
License Plate: KV75ZVGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	 0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	 0
AB (Airbag)	 4
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (4)

AB (Airbag) (4 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History
B2615:00	Airbag control unit (ACU) & cluster airbag lamp CAN message mismatch	History
B2617:00	Cluster airbag warning lamp CAN message timeout	History

Technician Notes

2017304629

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.