



Shop: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20240725132852

Test Time: 2024-07-25 13:28:52

Technician: Travino

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/Santro (AH2)--

VIN: MALAF51CLNM181544

Odometer Reading: 27251km

License Plate: KR24RKGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT

Version: V13.80

Serial Number: VB8GJCC01514

Repair Order Number: --

## System Scanned( 6 )

System	Status/DTC
ENG (Engine)	0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	0
AB (Airbag)	0
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
EPS (Motor Driven Power Steering)	0

## DTC ( 0 )

## Technician Notes

2016467642

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

