Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Atos/--
VIN: MALAF51CLNM186462

Odometer Reading: 105429KM
License Plate: MF67PDGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.15

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	2
AB (Airbag)	2
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
EPS (Motor Driven Power Steering)	0

DTC (4)

ABS/ESC (Anti Lock Brake/Electronic Stability Control) (2 DTCs)

DTC	Description	Status
C1207:02	Left rear wheel speed sensor (WSS) range/performance/Intermittent	History
C1210:02	Right rear vehicle speed sensor (VSS) range/performance/Intermittent	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History

Technician Notes

2017326167

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.