



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250507114018
Test Time: 2025-05-07 11:40:18
Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Santro (AH2)/--
VIN: MALAF51CYNM170043

Odometer Reading: 87364km
License Plate: KL18YZGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.86

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
ENG (Engine)	 0
AMT (Automated Manual Transmission)	 1
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	 0
AB (Airbag)	 3
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 1
E-ST (E-Shifter)	 1

DTC (6)

AMT (Automated Manual Transmission) (1 DTC)

DTC	Description	Status
P0820:16	TGS Lever undervoltage	History

AB (Airbag) (3 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History
B1328:00	Driver front impact sensor (FIS) defect	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History



E-ST (E-Shifter) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes
2016867824

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.