Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/GRAND i10/--
VIN: MALB251ALNM252016

Odometer Reading: 138819KM
License Plate: KK11HJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
ENG (Engine)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	3
CLU (Cluster Module)	0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	2
IBU-BCM (Integrated Body Control Unit-Body Control Module)	0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	0
ICU (Integrated Central Control Unit)	3

DTC (8)

AB (Airbag) (3 DTCs)

DTC	Description	Status
B1101:00	Battery voltage high	History
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History

EPS (Motor Driven Power Steering) (2 DTCs)

DTC	Description	Status

C1102:16	Battery voltage low	History
C1633:83	Cluster counter invalid	History

ICU (Integrated Central Control Unit) (3 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B251E:00	Left stop lamp circuit short to ground	History
B251F:00	High mounted stop lamp circuit short to ground	History

Technician Notes

2017317246

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.