# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/GRAND i10(AI3)/--
VIN: MALB251ALPM367854

Odometer Reading: 81680KM
License Plate: KY26NHGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 11 )

| System | Status/DTC |
|---|---|
| ENG (Engine) | 0 |
| ABS/ESP (Anti Lock Brake/Electronic Stability Program) | 0 |
| AB (Airbag) | 0 |
| CLU (Cluster Module) | 0 |
| IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System) | 0 |
| CODE (Transmitter Code Saving) | 0 |
| EPS (Motor Driven Power Steering) | 0 |
| IBU-BCM (Integrated Body Control Unit-Body Control Module) | 0 |
| IBU-SMK (Integrated Body Control Unit-Smart Key Unit) | 0 |
| IBU-IMMO (Integrated Body Control Unit-Immobilizer) | 0 |
| ICU (Integrated Central Control Unit) | 2 |

## DTC ( 2 )

### ICU (Integrated Central Control Unit) ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| B251E:00 | Left stop lamp circuit short to ground | History |
| B251F:00 | High mounted stop lamp circuit short to ground | History |

## Technician Notes

2017316250

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*