



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250412085843
Test Time: 2025-04-12 08:58:43
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/GRAND i10(AI3)/--
VIN: MALB251ALPM369306

Odometer Reading: 57277km
License Plate: LG14NSGP

Customer Information

Name: Dekra MFC AUCTION HOUSE












Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.86

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(11)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 0

DTC (0)

Technician Notes
2016840596



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.