

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/GRAND i10(AI3)/--
VIN: MALB251ALPM417948

Odometer Reading: 72188KM
License Plate: LG03SSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (11)

System	Status/DTC
ENG (Engine)	✓ 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	✓ 0
AB (Airbag)	✓ 0
CLU (Cluster Module)	✓ 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	✓ 0
CODE (Transmitter Code Saving)	✓ 0
EPS (Motor Driven Power Steering)	✓ 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	✓ 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	✓ 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	✓ 0
ICU (Integrated Central Control Unit)	✓ 0



DTC (0)

Technician Notes

2017304174

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.