Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/GRAND i10(AI3)/--
VIN: MALB251ALRM522570

Odometer Reading: 115918KM
License Plate: LT71SKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
ENG (Engine)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	2
AB (Airbag)	1
CLU (Cluster Module)	0
EPS (Motor Driven Power Steering)	1

DTC (4)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1102:01	Battery voltage low	Active
C2402:01	Motor electrical fault	Active

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	Active

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes

2017316040

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.