

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/GRAND i10(AI3)/--
VIN: MALB251ALSM618315

Odometer Reading: 111620KM
License Plate: MH54HYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 2
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 3

DTC (5)

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History

ICU (Integrated Central Control Unit) (3 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History

B2602:00	Left headlamp low beam circuit open	History
B2603:00	Right headlamp low beam circuit open	History

Technician Notes
2017302483

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.