Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(BI3)/--
VIN: MALBG511VNM091627

Odometer Reading: 131774KM
License Plate: KG30HKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (16)

System	Status/DTC
ENG (Engine)	0
A/T (Transaxle)	1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	1
CLU (Cluster Module)	0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	2
AVN (Audio Video Navigation) ADAS	0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	0
WPC (Wireless Power Charger)	0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	0
ICU (Integrated Central Control Unit)	0
RVM (Rear View Monitor) ADAS	0
IMT (Intelligent Manual Transmission)	1

DTC (5)

A/T (Transaxle) (1 DTC)

DTC	Description	Status
P0820:16	TGS Lever undervoltage	History

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (2 DTCs)

DTC	Description	Status
C1711:04	Improper program termination	Active
C2413:01	Motor current fail (overcurrent)	Active

IMT (Intelligent Manual Transmission) (1 DTC)

DTC	Description	Status
P0820:16	Gear lever X-Y Position sensor circuit	History

Technician Notes

2017305669

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.