Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(BI3)/--
VIN: MALBG512LNM135787

Odometer Reading: 87249KM
License Plate: KX25ZFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System		Status/DTC
ENG (Engine)		0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)		0
AB (Airbag)		1
CLU (Cluster Module)		0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)		0
CODE (Transmitter Code Saving)		0
EPS (Motor Driven Power Steering)		0
AVN (Audio Video Navigation)	ADAS	0
IBU-BCM (Integrated Body Control Unit-Body Control Module)		0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)		0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)		0
ICU (Integrated Central Control Unit)		0
RVM (Rear View Monitor)	ADAS	0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

2017311362

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.