Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(BI3)/--
VIN: MALBG512LPM196131

Odometer Reading: 111155KM
License Plate: LB67DPGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
ENG (Engine)	1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	1
CLU (Cluster Module)	0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	1
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
AVN (Audio Video Navigation) ADAS	0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	1
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	1
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	1
ICU (Integrated Central Control Unit)	0
RVM (Rear View Monitor) ADAS	0

DTC (6)

ENG (Engine) (1 DTC)

DTC	Description	Status
P2237:00	Oxygen sensor pumping current circuit/Open (Bank 1 sensor 1)	Pending

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System) (1 DTC)

DTC	Description	Status
B1603:00	CAN Bus off (B-CAN)	History

IBU-BCM (Integrated Body Control Unit-Body Control Module) (1 DTC)

DTC	Description	Status
B1603:00	CAN Bus off (B-CAN)	History

IBU-SMK (Integrated Body Control Unit-Smart Key Unit) (1 DTC)

DTC	Description	Status
B1603:00	CAN Bus off	History

IBU-IMMO (Integrated Body Control Unit-Immobilizer) (1 DTC)

DTC	Description	Status
B1603:00	CAN Bus off (B-CAN)	History

Technician Notes

2017315252

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.