Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(BI3)/--
VIN: MALBG512LPM197066

Odometer Reading: 81405
License Plate: LD96TRGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System		Status/DTC
ENG (Engine)		1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)		0
AB (Airbag)		2
CLU (Cluster Module)		0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)		1
CODE (Transmitter Code Saving)		0
EPS (Motor Driven Power Steering)		1
AVN (Audio Video Navigation)	ADAS	0
IBU-BCM (Integrated Body Control Unit-Body Control Module)		1
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)		1
IBU-IMMO (Integrated Body Control Unit-Immobilizer)		1
ICU (Integrated Central Control Unit)		2
RVM (Rear View Monitor)	ADAS	0

DTC (10)

ENG (Engine) (1 DTC)

DTC	Description	Status
P00B7:00	Engine coolant flow low/performance	Active

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2617:00	Cluster airbag warning lamp CAN message timeout	History

IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System) (1 DTC)

DTC	Description	Status
P1678:00	Immobilizer engine management system (EMS) no request (EMS Data circuit open, no immobilizer)	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

IBU-BCM (Integrated Body Control Unit-Body Control Module) (1 DTC)

DTC	Description	Status
P1678:00	Immobilizer engine management system (EMS) no request (EMS Data circuit open, no immobilizer)	History

IBU-SMK (Integrated Body Control Unit-Smart Key Unit) (1 DTC)

DTC	Description	Status
P1678:00	Immobilizer engine management system (EMS) no request (EMS Data circuit open, no immobilizer)	History

IBU-IMMO (Integrated Body Control Unit-Immobilizer) (1 DTC)

DTC	Description	Status
P1678:00	Immobilizer engine management system (EMS) no request (EMS Data circuit open, no immobilizer)	History

ICU (Integrated Central Control Unit) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2524:00	Right front turn signal lamp circuit short to ground	History

Technician Notes

2017316013

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.