



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250507114531
Test Time: 2025-05-07 11:45:31
Technician: Travino

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Creta (GS)/--
VIN: MALC381UMHM237641
Odometer Reading: 204380
License Plate: NO r e g

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.86
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
ENG (Engine)	✓ 0
A/T (Transaxle)	✓ 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	✓ 0
AB (Airbag)	✗ 1
CLU (Cluster Module)	✓ 0
IMMO (Immobilizer)	✓ 0
CODE (Transmitter Code Saving)	✓ 0
EPS (Motor Driven Power Steering)	✗ 1
BCM (Body Control)	✓ 0
SJB (Smart Junction Block)	✓ 0

DTC (2)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History

Technician Notes

2016867682



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.