

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/VENUE(QXI)/--
VIN: MALFB81ALMM169828

Odometer Reading: 76612KM
License Plate: KB23VZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 1
AB (Airbag)	 1
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 1

DTC (4)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1209:01	Right rear vehicle speed sensor (VSS) circuit open or short	History

AB (Airbag) (1 DTC)

DTC	Description	Status
-----	-------------	--------

B1102:00	Battery voltage low	History
----------	---------------------	---------

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

ICU (Integrated Central Control Unit) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes
2017304875

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.