Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/VENUE(QXI)/--
VIN: MALFB81AVMM169859

Odometer Reading: 119041KM
License Plate: JZ46LRGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (14)

System	Status/DTC
ENG (Engine)	0
A/T (Transaxle)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	1
AB (Airbag)	2
CLU (Cluster Module)	0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	0
A/C (Air Conditioner)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	1
IBU-BCM (Integrated Body Control Unit-Body Control Module)	0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	0
ICU (Integrated Central Control Unit)	1
IMT (Intelligent Manual Transmission)	0

DTC (5)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1623:08	CAN Timeout - Steering angle sensor (SAS)	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

ICU (Integrated Central Control Unit) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

2017307436

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.