

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/VENUE(QXI)/--  
VIN: MALFB81BLPM405656

Odometer Reading: 42024KM  
License Plate: BK66ZBZN

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT  
Version: V14.10

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned ( 12 )

| System                                                                  | Status/DTC                                                                              |
|-------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|
| ENG (Engine)                                                            |  0   |
| ABS/ESP (Anti Lock Brake/Electronic Stability Program)                  |  0   |
| AB (Airbag)                                                             |  2   |
| CLU (Cluster Module)                                                    |  0  |
| IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System) |  0 |
| A/C (Air Conditioner)                                                   |  0 |
| CODE (Transmitter Code Saving)                                          |  0 |
| EPS (Motor Driven Power Steering)                                       |  0 |
| IBU-BCM (Integrated Body Control Unit-Body Control Module)              |  0 |
| IBU-SMK (Integrated Body Control Unit-Smart Key Unit)                   |  0 |
| IBU-IMMO (Integrated Body Control Unit-Immobilizer)                     |  0 |
| ICU (Integrated Central Control Unit)                                   |  0 |

## DTC ( 2 )

### AB (Airbag) ( 2 DTCs )

| DTC      | Description                                                          | Status  |
|----------|----------------------------------------------------------------------|---------|
| B2615:00 | Airbag control unit (ACU) & cluster airbag lamp CAN message mismatch | History |
| B2617:00 | Cluster airbag warning lamp CAN message timeout                      | History |

## Technician Notes

2017330186

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.