Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/CRETA(SU2i)/ALCAZAR(PS7i)/--
VIN: MALPC815MPM835280

Odometer Reading: 25286KM
License Plate: MN15XGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (16)

System	Status/DTC
ENG (Engine)	0
A/T (Transaxle)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	0
CLU (Cluster Module)	0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	0
A/C (Air Conditioner)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	0
WPC (Wireless Power Charger)	0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	0
ICU (Integrated Central Control Unit)	0
RVM (Rear View Monitor) ADAS	0
SHVU (Seat Heater Ventilation control Unit)	0
MLM (Mood Lamp Module)	0

DTC (0)

Technician Notes

2017314067

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.