

TATA VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/TATA/TIAGO/--
VIN: MAT626601SKR89587

Odometer Reading: 29813
License Plate: HNK317L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V2.20

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (1)

System	Status/DTC
EMS(Engine Management System)	 1

DTC (1)

EMS(Engine Management System) (1 DTC)

DTC	Description	Status
P0328-85	DTC description not available	Temporary

Technician Notes

2017303182

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.