

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Fronx/--

VIN: MBHKWDA3S00258648

Odometer Reading: 41384

License Plate: LV42ZMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V4.91

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned (11)

System	Status/DTC
ECM/PCM(Engine/powertrain)	 0
TCM(Transmission Control Module)	 0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	 2
SRS(Airbag)	 0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	 0
CGW(Central gateway control module)	 0
EPS(Power steering)	 0
BCM(Body Control Module)	 2
LTS(Lighting and turn signal)	 0
ADM(360 view camera)	  1
HUD(Head-up display)	  0

DTC (5)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1157-1C	Power supply voltage abnormal	History
C1161-07	Pump motor circuit	History

BCM(Body Control Module) (2 DTCs)

DTC	Description	Status
B140B-00	Remote controller battery low	History
B150A-13	Sunload Sensor Circuit Open	Current

ADM(360 view camera) (1 DTC)

DTC	Description	Status
B1D02-00	Rear camera signal fault	History

Technician Notes
2017302476

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.