



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250811120743
Test Time: 2025-08-11 12:07:43
Technician: Andrick

Maruti Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Maruti Suzuki/Swift/--
VIN: MBHZCDESR00244347

Odometer Reading: 14756
License Plate: MF69KGGP

Customer Information

Name: Dekra MFC AUCTION HOUSE





Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V4.80

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine/powertrain	 0
TCM	 0
ABS/ESP	 0
Airbag	 0
Instrument Panel Cluster (IPC)/meter/M&A	 0
Central gateway control module	 0
Power steering	 0
BCM	 0

DTC (0)

Technician Notes

2016975241

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

