Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261021112440
Test Time: 2026-10-21 11:24:40
Technician: Andrick

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Swift/--
VIN: MBHZCDESR00556336

Odometer Reading: 775
License Plate: NC10BKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	0
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	0
CGW(Central gateway control module)	0
EPS(Power steering)	0
BCM(Body Control Module)	0

DTC (0)

Technician Notes

2017315269

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.