# Nissan VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Nissan/Almera/--
VIN: MDHBBAN17Z0727666

Odometer Reading: 318358km
License Plate: JC49XFGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 8 )

| System | Status/DTC |
|---|---|
| Engine | 0 |
| Transmission | 0 |
| ABS | 1 |
| Air bag | 2 |
| Meter/M&A | 0 |
| Electric Power Steering (EPS)/DAST 3 | 3 |
| BCM | 4 |
| IPDM E/R | 0 |

## DTC ( 10 )

### ABS ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| U1002 | System communication (CAN) | Past |

### Air bag ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| B1049 | Driver airbag module | Crnt |
| B1065 | Assist airbag module | Crnt |

### Electric Power Steering (EPS)/DAST 3 ( 3 DTCs )

| DTC | Description | Status |
|---|---|---|
| C1601 | Battery VOLT | Past |
| U1000 | CAN communication circuit | Past |
| C1609 | CAN Vehicle speed | Past |

### BCM ( 4 DTCs )

| DTC | Description | Status |
|---|---|---|

| | | |
|---|---|---|
| U1000 | CAN communication circuit | Past |
| B2190 | Nissan anti-theft system (NATS) antenna AMP | Past |
| B2191 | Difference of key | Past |
| B2193 | Chain of BCM-ECM | Past |

## Technician Notes

2017317717

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*