



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250506162955
Test Time: 2025-05-06 16:29:55
Technician: Werner

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Nissan Magnite/--
VIN: MDHFBADD0Z0006648

Odometer Reading: 62159
License Plate: KS84HTGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.10

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(11)

System	Status/DTC
Engine	0
Transmission	0
ABS	4
Air bag	0
Electric Power Steering (EPS)/DAST 3	1
BCM	5
Cluster	2
HVAC	0
Multi AV	5
Hands-free module	0
GWD 2	0

DTC (17)

ABS (4 DTCs)

DTC	Description	Status
C1073:1C	Vacuum sensor circuit 4.DEF	Past
C1080:87	Injection multiplex EMS lost 2.DEF	Past
C1082:87	No sequential g/b mltiplx sig 2.DEF	Past
C1083:87	Steering wheel angle sensor multiplex signals	Past

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
-----	-------------	--------



C1601:16	Battery voltage 1.DEF	Past
----------	-----------------------	------

BCM (5 DTCs)

DTC	Description	Status
B1563:01	Brake pedal contact circuit 1.DEF	Past
C1A60:7B	Under inflated ---	CRNT
C1A85:68	Wheel valve sensor 4 ---	Past
C1A72:7A	Wheel 1 flat ---	Past
C1A73:7A	Wheel 2 flat ---	CRNT

Cluster (2 DTCs)

DTC	Description	Status
B1411:13	Oil pressure input CO	CRNT
U3003:16	ECU power supply 1.DEF	Past

Multi AV (5 DTCs)

DTC	Description	Status
B130B:1C	Right rear speaker 1.DEF	Past
B130D:1C	Right front speaker 1.DEF	Past
B1311:1C	Left rear speaker 1.DEF	Past
B130F:1C	Left front speaker 1.DEF	Past
B1324:13	GPS antenna CO	Past

Technician Notes
2016866851

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.