Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Nissan Magnite/--
VIN: MDHFBADD0Z0009549

Odometer Reading: 54035
License Plate: LGF070NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
Engine	2
Transmission	0
ABS	5
Air bag	1
Electric Power Steering (EPS)/DAST 3	1
BCM	4
HVAC	1
Multi AV	1
Hands-free module	0
GWD 2	0

DTC (15)

Engine (2 DTCs)

DTC	Description	Status
P155D:00	Generator	1 time
P2562:00	Turbocharger boost control position sensor A	Past

ABS (5 DTCs)

DTC	Description	Status
C1056:16	ECU supply voltage 1.DEF	Past
C1073:1C	Vacuum sensor circuit 4.DEF	Past
C1080:87	Injection multiplex Engine Management System (EMS) lost 2.DEF	Past
C1082:87	No sequential gearbox mltiplx sig 2.DEF	Past

C1083:87	Steering wheel angle sensor multiplex signals	Past

Air bag (1 DTC)

DTC	Description	Status
B1036:16	Power supply voltage ---	Past

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
C1601:16	Battery voltage 1.DEF	Past

BCM (4 DTCs)

DTC	Description	Status
B1520:14	Starter relay CO.0	Past
B1528:19	Left LED indicator 2.DEF	Past
B1529:19	Right LED indicator 2.DEF	Past
C1A60:7B	Under inflated ---	Crnt

HVAC (1 DTC)

DTC	Description	Status
B24A1:16	ECU supply voltage 1.DEF	Past

Multi AV (1 DTC)

DTC	Description	Status
B1351:4B	ECU 1.DEF	Past

Technician Notes

2017316038

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.