

Shop Name: --Tel: --Email: --Address: --

Report ID: MAXIA20250829160401 Test Time: 2025-08-29 16:04:01

Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Nissan Magnite/--VIN: MDHFBADD0Z0016332

Odometer Reading: 44352 License Plate: LJ55ZVGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V10.30

Serial Number: VB8GJCC01509 Repair Order Number: --

System Scanned(12)

System		Status/DTC
Engine		O
Transmission		② 0
ABS		Q 1
Air bag		② 0
Electric Power Steering (EPS)/DAST 3		② 0
BCM		Q 7
Cluster		Q 1
HVAC		② 0
Multi AV		Q 1
Hands-free module		② 0
GWD 2		② 0
AVM	APAS	② 0

🔼 DTC (10)

ABS (1 DTC)

DTC	Description	Status
C1082:87	No sequential gearbox mltiplx sig 2.DEF	Past
BCM (7 DTCs		
DTC	Description	Status
B1528:19	Left LED indicator 2.DEF	Past
B1529:19	Right LED indicator 2.DEF	Past
C1A60:7B	Under inflated	Crnt

AUTEL www.autel.com

MaxiSys MS906 BT

/Nissan/Nissan I	Magnite	Test Time: 2025-08-29 16:04:01	Report ID: MAXIA20250829160401
C1A82:68	Wheel valve sensor 1		Past
C1A84:68	Wheel valve sensor 3		Past
C1A72:7A	Wheel 1 flat		Past
C1A74:7A	Wheel 3 flat		Past
Cluster (1 DTC	()		
DTC	Description		Status
B1411:13	Oil pressure input CO		Past
Multi AV (1 D)	rc)		
DTC	Description		Status
B1351:4B	ECU 1.DEF		Past
Technician N 2016996317	otes		
		Customer name:	

Note:Please save a copy of this report for your records.

Technician:

Date: _____

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2