

Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20241014150025  
Test Time: 2024-10-14 15:00:25  
Technician: Werner

# Nissan VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Nissan/Nissan Magnite/--  
VIN: MDHFBADD0Z0020867

Odometer Reading: 17688km  
License Plate: KZS501NW

## Customer Information

Name: Dekra MFC AUCTION HOUSE





Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V9.90

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 7 )

System	Status/DTC
Engine	 2
ABS	 1
Air bag	 0
Electric Power Steering (EPS)/DAST 3	 0
BCM	 5
Cluster	 2
HVAC	 1

## DTC ( 11 )

### Engine ( 2 DTCs )

DTC	Description	Status
P0657:11	Main relay control circuit CC.0	Past
P0560:16	ECU supply voltage 2.DEF	Past

### ABS ( 1 DTC )

DTC	Description	Status
U3003	ECU power supply 1.DEF	Past

### BCM ( 5 DTCs )

DTC	Description	Status
C1A80:55	Tire pressure monitor function 1.DEF	CRNT
C1A82:68	Wheel valve sensor 1 ---	CRNT
C1A83:68	Wheel valve sensor 2 ---	CRNT



C1A84:68	Wheel valve sensor 3 ---	CRNT
C1A85:68	Wheel valve sensor 4 ---	CRNT

Cluster ( 2 DTCs )

DTC	Description	Status
U3003:16	Battery voltage 1.DEF	Past
B1412:11	External temperature sensor circuit CC.0	Past

HVAC ( 1 DTC )

DTC	Description	Status
B24C6:14	Blower motor control circuit CO.0	Past

Technician Notes

2016569638

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.