

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Nissan Magnite/--
VIN: MDHFBADD0Z0032299

Odometer Reading: 13785
License Plate: LGK065MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned (10)

System	Status/DTC
Engine	 8
ABS	 2
Air bag	 1
Electric Power Steering (EPS)/DAST 3	 4
BCM	 8
HVAC	 3
Multi AV	 2
IPDM E/R	 5
Hands-free module	 3
GWD 2	 0

 DTC (36)

Engine (8 DTCs)

DTC	Description	Status
P060A:49	ECU 1.DEF	Past
C006C:64	Trajectory control function 1.DEF	Past
P0901:96	Clutch motor 5.DEF	Past
P1711:38	Clutch information unavailable 1.DEF	Past
P1712:38	Clutch information unavailable 1.DEF	Past
P0901:29	Clutch motor 2.DEF	Past
P0733:63	Forward emergency braking (FEB) default OFF/ON switch 2.DEF	Past
P0736:96	Whl speed coherence 3.DEF	Past

ABS (2 DTCs)

DTC	Description	Status
C1083:87	Steering wheel angle sensor multiplex signals	Past
C1082:86	No sequential gearbox mltiplx sig 1.DEF	Past

Air bag (1 DTC)

DTC	Description	Status
B1036:16	Power supply voltage ---	Past

Electric Power Steering (EPS)/DAST 3 (4 DTCs)

DTC	Description	Status
C1601:16	Battery voltage 1.DEF	Past
U214F:87	BCM not detected by Electric Power Steering (EPS) CAN-V 1.DEF	Past
C161B:86	Information multiplex vehicle speed invalid 1.DEF	Past
U2140:87	ECM not detected by Electric Power Steering (EPS) CAN-V 1.DEF	Past

BCM (8 DTCs)

DTC	Description	Status
B1528:19	Left LED indicator 2.DEF	Past
B1529:19	Right LED indicator 2.DEF	Past
C1A60:7B	Under inflated ---	Past
C1A80:55	Tire pressure monitor function ---	Crnt
C1A82:68	Wheel valve sensor 1 ---	Past
C1A83:68	Wheel valve sensor 2 ---	Past
C1A84:68	Wheel valve sensor 3 ---	Past
C1A85:68	Wheel valve sensor 4 ---	Past

HVAC (3 DTCs)

DTC	Description	Status
B24A1:16	ECU supply voltage 1.DEF	Past
B24B4:02	Control panel 1.DEF	Past
B24D4:08	A/C control communication 1.DEF	Past

Multi AV (2 DTCs)

DTC	Description	Status
B1341:16	Compressor configuration 3.DEF	Past
B1315:11	FM 1 receiver 1.CC.0	Past

IPDM E/R (5 DTCs)

DTC	Description	Status
-----	-------------	--------

B1227:81	CAN communication circuit	Past
B1257:15	Side lamps CO.1	Crnt
B1270:94	Comb stalk undr str whl circ	Past
B1286:14	Left low beam headlamp circuit	Past
B1287:14	Right low beam headlamp circuit	Past

Hands-free module (3 DTCs)

DTC	Description	Status
B2070:68	Fault memory 1.DEF	Past
B2051:11	Steering lock CC.0	Past
B2057:1C	Steering column lock protection 1.DEF	Past

Technician Notes
2017301041

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.