



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250619135015
Test Time: 2025-06-19 13:50:15
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Datsun Go/--
VIN: MDHJBAAD0Z0504835

Odometer Reading: 145205km
License Plate: KXF708MP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine	 2
Transmission	 1
ABS	 1
Air bag	 3
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 2
BCM	 1
IPDM E/R	 1

DTC (11)

Engine (2 DTCs)

DTC	Description	Status
P1610	Lock mode	Past
P1612	Chain OF ECM-IMMU	Past

Transmission (1 DTC)

DTC	Description	Status
P1586	G sensor	Crnt

ABS (1 DTC)

DTC	Description	Status
C1109	Battery voltage (abnormal)	Past

Air bag (3 DTCs)

DTC	Description	Status
-----	-------------	--------



B0010:13	Assist airbag module	Past
B0001:13	Driver airbag module	Past
B142A:16	Ignition voltage	Past

Electric Power Steering (EPS)/DAST 3 (2 DTCs)

DTC	Description	Status
C1601	Battery VOLT	Past
C1608	Control unit	Past

BCM (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

IPDM E/R (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Technician Notes

2016915581

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.